	!			
Work Order ID 79295  January-24-12 1:54:18 PM	*792	295*		Page 1
	*2* *2*	*N900040100  Cust Item ID: Customer:	↑* Setup Start	ובימו
Approvals: Process Plan: M.L.J Date: \Gamma QC: Date:	2\01\2\frac{1}{2\frac{1}{2}} Tooling: SPC (Y/N):	Date:	Run Start	NRI
Sequence ID/ Operation Work Center ID Description	Set Up/ Run Hours	Tool ID Tool # Plan Code	Accept Reject Qty Qty	Reject Insp. Number Stamp
Draw Nbr Revision Nbr	in the second se			
. D3187 Rev C	<u> </u>			
*100  *100  *100  *100  *LOW WATER JET  Memo  FLOW CNC Waterjet  GG 1. 050  Deburr if necessary	0.00  Dwg Rev:Prog Rev:	<u>C</u> 2-	20	Jm 12-6.
QC2- Inspect parts off machine FAI/F,  *110  QC2- Inspect parts off machine FAI/F,  Memo  Quality Control  ***TEMPLATE DT3187-	0.00		2 0	<u> </u>
QC8- Inspect parts - second check  *190* QC Memo	0.00 Salacit			

Dart Aerospace	Ltd
----------------	-----

W/O: WORK ORDER CHANGES							,
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							-
			ļ				
						<u> </u>	

Part No:	·	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:	
	Resolution:		Disposition:	QA: N/C Closed	l:	Date:	

NCR:			WORK ORD	ER NON-CONFORMAN	CE (NCR)			
		Description of NC		Corrective Action Section E		Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
		•			_			
•		• ,						
<del></del>								

Work Ord January-24-12		295		*792	95*			<u></u>			Page 2
Item ID: Revision ID: Item Name:	D3187-2 Spacepod Flo	or		Accept	*N900	 0040	100	)*	Setup Start Stop	*NS	11*
Start Date: Required Date: Reference:	24/01/2012 07/02/2012	Start Qty: 2.00 Req'd Qty: 2.00	*2* *2*		Cust Item ! Customer:	ID:				IVI	
Approvals:	Process Pla	n:	Date:		·	ate:	 <del></del>	I	Run Start Stop	*NR	?1* <sup>-</sup> ?2*
Sequence ID/ Work Center II 130 *120* HandFinish Hand Finishing	D	Operation Description Chemical Conversion Co	oat per QS1005 4.1	Set Up/ Run Hours 0.00	Tool ID	Tool#	Plan Code	Accept Qty			nsp. stamp
*140  *140  *140  Powdercoat  Powder Coating  M \ 2	1279	Black Sandtex(Ref.4.3.5.  Memo START TIM	E: 174	0.00 5 0.00 OVEN TEMPERATURE  2-75	:		(	QX.	- J -		ML 12/06/18
150 *150* QC Quality Control		QC3- Inspect Part Finish  Memo		0.00				2	ф		1068.

Dart Aerospace Ltd
--------------------

	WORK ORDER	CHANGES				
STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			<del></del> .			
					<u> </u>	
					į	
	STEP		STEP PROCEDURE CHANGE By			STEP PROCEDURE CHANGE By Date Qty Chief Eng /

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
Resolution:		Disposition:	QA: N/C Closed	l:	Date:

NCR:		,	WORK ORD	ER NON-CONFORMAN	CE (NCR)			
-	1	Description of NC		Corrective Action Section B		Verification	Approval	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC Inspector
						'		
					ł			
					;			
	1							

1 m

Dart Aerospace I	Ltd
------------------	-----

W/O:		WORK ORDER C	HANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval OC Inspector
						ı	
				· · · · · · · · · · · · · · · · · · ·			

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
Resolution:		Disposition:	QA: N/C Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
DATE STEP	Description of NC		Corrective Action Section B		Verification	Approval	Approval QC inspector				
	Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng					
<del> </del>					+						
				<del></del>							

Work Order ID 79295  January-24-12 1:54:18 PM			<del></del>	*792	95*							Page	4
Item ID: Revision ID: Item Name:	D3187-2 Spacepod Floo	or	·	Accept	*N9000	140	100	)*	Setup	Start Stop	1/1	S1* S2*	
Start Date: Required Date: Reference:	24/01/2012 07/02/2012	Start Qty: 2.00 Req'd Qty: 2.00	*2* *2*		Cust Item ID Customer:	:							
Approvals:	Process Pla	nn:	Date:	Tooling: SPC (Y/N):	Date				Run	Start Stop	*N! *N!	R1* R2*	
Sequence ID/ Work Center II 190 *1 QA QC Quality Control	<u> </u>	Operation Description QC21- Final Inspection Memo	- Work Order Reteasc	Set Up/ Run Hours 0.00	Tool ID	Tool#	Plan Code	Accept Qty	Qty		Reject Number	Insp. Stamp	

R13-08.36

Dart Aerospace	<b>Ltd</b>
----------------	------------

W/O:	W/O: WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						1	
						is .	
		<u> </u>					
							,
					<u> </u>		

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
Resolution:		Disposition:	QA: N/C Closed:	Date:

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Verification	Approval	Annroyal			
DATE ST	STEP	STEP Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC Inspector			
	<del>                                     </del>				<del> </del>		<u> </u>				
								1			
				<del> </del>							
								:			

**Picklist Print** Page 1 January-24-12 1:54:22 PM Work Order ID: 79295 \*79295\* Parent Item: D3187-2 \*D3187-2\* Parent Item Name: Spacepod Floor Start Date: 24/01/2012 Required Date: 07/02/2012 Start Qty: 2.00 Required Qty: 2.00 Comments: IPP: C05.04.14Now a purchased partKJ/JLM IPP Rev:D Now on Waterjet 07-04-19 JLM IPP Rev:E Now Powder Coated 07-05-24 JLM IPP Rev:F 09-01-20 rev.C as per dwg DD verified by:EC Component Item ID/ Replacement Mfg/ Bin **Primary** Last Route Unit of Qty on Qty per Kit Qty Total Date Status Item Name Item ID Purch Item Location Measure Hand Location Seq ID Qty Issued Issued D2986-1 Manufactured No 110 Each 2.0000 1 \*\* Rubber Spacer Location Loc Code ST242 60770 2 M6061T6S.050 Purchased No 160 sf 119.3600 \*M6061T6S 050\* \*\* JM 12-6-15 6061-T6 .050 Sheet Location Loc Oty Loc Code MAT021 119.36 113216 15

89.36

15

114799

114993

121192

(7.825 SF)

121192. (7.825 SF)

## Dart Aerospace Ltd

WORK ORDER CHANGES							
STEP	PROCEDURE CHANGE				Approval Chief Eng / Prod Mgr	Approval QC Inspector	
	STEP					STEP PROCEDURE CHANGE By Date Qty Chief Eng /	

Part No:	PAR #:	Fault Category:	N	CR: Yes No	DQA:	Date: _	
Resolution:		Disposition:	Q	A: N/C Closed	<b>.</b>	Date:	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC	Corrective Action Section B				Approval	A			
DATE STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Chief Eng	Approval QC Inspector				
						·					
							ì	] }			
					_						
								<u>.</u>			
•							l				

DART AEROSPACE LTD	Work Order:	79295
Description: Spacepod Floor	Part Number:	D3187-2
Inspection Dwg: D3187 Rev: C		Page 1 of 1

## FIRST ARTICLE INSPECTION CHECKLIST


	<del></del>	T TAKE TO LET II	1	,	T	
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø0.250	+0.005/-0.001	0,252"			V	mind.
Ø0.19	+0.005/-0.001	0, 190"	-		V	mmol
19.87	+/-0.030	19.87"	~		MT	HBOI
53.44	+/-0.030	53.44	~		mī	HBO!

r					
Measured by:	SM	Audited by:	9	Preliminary Approval:	N/A
Date:	12-6-15	Date:	12/06/15.	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	07.06.04	New Issue	KJ/JLM . n	1-1-1-1
В	10.08.03	Dimensions updated to Dwg Rev C	KJ 4	1
				(41.3

Dart Aerospa	ace Ltd
--------------	---------

W/O:			V	ORK ORDER CHANGE	S				
DATE	STEP	PROC	PROCEDURE CHANGE				Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
,									
							ļ		
							!		
<u> </u>			<u>.</u>				l		
Part No	:	PAR #:	_ Fault Ca	tegory:	NCR: Yes N	lo DQA	\:	_ Date: _	
	R	esolution:	_ Disposit	ion:	QA: N/C Clo	sed:		Date: _	
NCR:		W	ORK OR	DER NON-CONFORMAL	NCE (NCR)				
DATE	STEP	Description of NC		Corrective Action Section		Verifica		Approval	Approval
DAIL	SILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sectio	n C	Chief Eng	QC Inspector
ļ							!		
					-			<u> </u>	
<u> </u>									
								•	
1		Į.							l




Dart Aerospace	e Ltd	
----------------	-------	--

	WORK ORDER C					
rep	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						<u> </u>
<u> </u>	EP	PROCEDURE CHANGE	EP PROCEDURE CHANGE By	EP PROCEDURE CHANGE By Date	EP PROCEDURE CHANGE By Date Qty	EP   PROCEDURE CHANGE   By   Date   Qty   Chief Eng /

Part No:	<del></del>	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:	
	Resolution:		Disposition:	QA: N/C Closed	l:	Date:	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
	1	Description of NC		Corrective Action Section B		Verification	Ammyayal	Approval			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	QC Inspector			
						 		]			
						-					
						   		;			
								<u> </u>			
					}						



W/O:		WORK ORDER CHANGES										
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
						·						
	<u> </u>				<u> </u>	<u> </u>	<u> </u>					

Part No:	<del></del>	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
F	Resolution:		Disposition:	QA: N/C Closed	:	Date:

NCR:		V	ORK OR	DER NON-CONFORMANC	E (NCR)			
		Description of NC		Corrective Action Section B		Verification	Approval Chief Eng	Approval QC Inspector
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		
	<del> </del>	·			<del>-</del>			
			ļ					
<del></del>								
							li.	
							E	
	<u> </u>					į.		